

(Provincial)

900192

Serial No. ST

27/05/2021

Received from Alkal Academy Day Boarding  
English Medium co-educational school, Mander  
with letter No.....dated.....20

the sum of Rupees..15,000/-  
(ਪੰਦਰਾਂ ਹਜ਼ਾਰ ਰੁਪਏ)

in Cash/by Cheque on account of.....

in Cash.....payment of ਸ਼ੁਕਰ ਚਿਕਿਤਸਾ ਨਿਗਮ  
ਵੀਸ

Rs.....Signature ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਪ੍ਰਤਕ ਉਪ ਮੰਡਲ, ਲ.ਨਿ.ਵਿ.

Designation (ਉਪ ਮੰਡਲ), ਬੁਢਲਾਡਾ  
22

ਦਫ਼ਤਰ : ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਨਸਾ।

ਟੈਲੀਫੋਨ/ਫੈਕਸ ਨੰ: 01652-232119

E Mail ID :- xen.mansa@gmail.com

Remove Watermark Now

ਪੱਤਰ ਨੰਬਰ .....1688

ਮਿਤੀ.....29-7-2020

ਵੱਲ

ਪ੍ਰਿੰਸੀਪਲ,

ਅਕਾਲ ਅਕੈਡਮੀ ਸ. ਸ. ਸਕੂਲ,

ਮੰਡੇਰ (ਮਾਨਸਾ)।

ਵਿਸ਼ਾ :- ਸਾਲ 2020-21 ਲਈ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਹਵਾਲਾ:- ਆਪ ਦਾ ਪੱਤਰ ਨੰ. AAM/22/2020-21 ਮਿਤੀ 24/07/2020

ਤੁਹਾਡੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਇੰਜੀਨੀਅਰ ਇੰਚਾਰਜ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ। ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਵੇਖਣ ਨੂੰ ਸੇਫ/ਠੀਕ ਜਾਪਦੀ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ 31/03/2021 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਨੱਥੀ/ ਸਰਟੀਫਿਕੇਟ

ਅਤੇ ਨਕਸ਼ਾ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ,

ਪ੍ਰਾਂਤਕ ਮੰਡਲ ਲੋ.ਨਿ.ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,

ਮਾਨਸਾ।



## Building Safety Report

NAME OF SCHOOL:- AKAL ACADEMY, MANDER (MANDER)  
(District- MANSA)

As per report of Vijay Kumar Assistant/Junior Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions.

1. The Parameters to check the stability and safety of building such as structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available
2. In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection of undersigned may be arranged and obtained a certification after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building 62382 Sft which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2020-2021

As per visually inspection as reported by the concerned Assistant/Junior Engineer the above building may be used for normal use for One year up to 31-03-2022 Subject to the above conditions.

Vijay Kumar  
Assistant/Junior Engineer

L.A.  
Sub Division Engineer,  
Provincial Sub Division,  
P.W.D. (B & R), Budhlada